User1: 02
User2: F12

Crew Signatures
Signed by MITCHELL, ANGENETTA [redacted] at 04/21/2024 07:18:45

REDACTED PUBLICATION COPY | Residential address removed

HUMAN FACTORS CONTRIBUTING: 3 Unattended Person
FIRE SUPPRESSION FACTORS: None
EQUIPMENT INVOLVED IN IGNITION: None
MOBILE PROPERTY INVOLVED: None

Narrative

E14 arrived OS to a 2 story residential structure no smoke or fire show , E14 assumed command and investigated. The residence had light smoke on both floors and the fire had been extinguished prior to E14 arrival. Per the home owner she was using her hookah and the hot stone fell on the hot plate igniting a fire. It was extinguished by a bystander prior to E14's arrival. Truck was requested for ventilation of structure. All units were dismissed by C2 except Tk and E14. the scene was left with TPD.

Structure

STRUCTURE TYPE: 3 Open structure
BUILDING STATUS: 2 In normal use
STORIES:
At or above Grade:2 Below Grade:0 Origin:2
FLAME DAMAGE PERCENTAGE:
<25:1 25 to 49:0 50 to 75:0 >75:0
FIRE SPREAD: 1 Confined to Object of Origin
FLAME SPREAD: None
MAIN FLOOR SIZE:
DETECTORS: 1 Smoke, 1 Battery Only, 2 Detector operated, 1 Alerted Occupants, Occupants Responded
AUTOMATIC EXT. SYSTEM: None
Hydrant w/in 1000 FT: Yes

Owner

OWNER: [redacted]
BUSINESS: [redacted]

Responding Units

Apparatus: DISTRICT CHIEF 2, Dispatched: 04/20/2024 11:43:22, En route: 04/20/2024 11:45:56, Arrival: 04/20/2024 11:50:33, Available: 04/20/2024 11:58:50
Apparatus: ENGINE 1, Dispatched: 04/20/2024 11:43:22, En route: 04/20/2024 11:45:40, Arrival: 04/20/2024 11:52:27, Available: 04/20/2024 11:58:49
Apparatus: ENGINE 3, Dispatched: 04/20/2024 11:43:22, En route: 04/20/2024 11:46:00, Arrival: 04/20/2024 11:50:33, Available: 04/20/2024 12:10:50
Apparatus: RESCUE 3, Dispatched: 04/20/2024 12:01:49, En route: 04/20/2024 12:01:58, Arrival: 04/20/2024 12:05:07, Available: 04/20/2024 12:21:16
Apparatus: TRUCK 14, Dispatched: 04/20/2024 11:43:22, En route: 04/20/2024 11:45:16, Arrival: 04/20/2024 11:51:29, Available: 04/20/2024 12:27:09

Exposures

No Crew Exposures.

Local

REDACTED PUBLICATION COPY | Residential address removed

TAMPA FIRE RESCUE
808 Zack St.
Tampa, Florida 33602

TAMPA FIRE RESCUE

Incident 240027274

Incident Date: 04/20/2024 11:42:38
Incident Number: 240027274
Incident Location:
[redacted]
Tampa, Hillsborough, FL 33629
ENGINE 14; Shift: A

INCIDENT #: 240027274 EXPOSURE #: 000
INCIDENT LOCATION: [redacted]
INCIDENT TYPE: 111 Building fire. Excludes confined fires.
ALARM: 04/20/2024 11:42:38
DISPATCH: 04/20/2024 11:43:22
EN ROUTE: 04/20/2024 11:44:58
FIRST RESPONDER ARRIVES: 04/20/2024 11:50:28
ARRIVAL: 04/20/2024 11:50:28
CONTROL: 04/20/2024 11:44:00
LAST UNIT CLEARED:04/20/2024 12:27:00
ACTION TAKEN:86 Investigate ; ;
RESPONDING UNITS:
Suppression [Apparatus:2 Personnel:7]
EMS [Apparatus:1 Personnel:3]
Other [Apparatus:2 Personnel:5]
DETECTOR ALERTED OCCUPANTS: Yes
HAZMAT RELEASE: N None
MIXED PROPERTY USE: NN Not Mixed
PROPERTY USE: 419 1 or 2 family dwelling
No mutual aid given or received
Lead Crew Member: MITCHELL, ANGENETTA [redacted]
Crew Member 2: GLASS, JACE [redacted]
Crew Member 3: THERIAULT, CAMERON [redacted]
Crew Member 4: RALSTON-CRANDALL, RILEY [redacted]

Fire Details

INVOLVED:
Living Units:1 Buildings:0
SIGNIFICANT ONSITE PRODUCTS: None
()
AREA OF FIRE ORIGIN: 72 Exterior balcony, unenclosed porch
HEAT SOURCE: 42 Molten, hot material
ITEM FIRST IGNITED: 81 Electrical wire, cable insulation
FIRE CONFINED TO OBJECT OF ORIGIN: Yes
TYPE MATERIAL IGNITED: 41 Plastic
CAUSE OF IGNITION: 2 Unintentional
FACTORS CONTRIB. TO IGNITION: None

REDACTED PUBLICATION COPY | Residential address removed

TYPE MATERIAL IGNITED: UU Undetermined
CAUSE OF IGNITION: 2 Unintentional
FACTORS CONTRIB. TO IGNITION: None
HUMAN FACTORS CONTRIBUTING: N None
FIRE SUPPRESSION FACTORS: None
EQUIPMENT INVOLVED IN IGNITION: None
MOBILE PROPERTY INVOLVED: None

Narrative

E3 ARRIVED OS TO 2 STORY CONCRETE STUCTURE NOTHING SHOWING. E3 STANDING BY AT HYDRANT.E3 FLUSHED HYDRANT. E3 ASSISTED E14,TK14 BY SECURING POWER.E3 RELEASED ON SCENE BY CHIEF 2. SCENE HANDLED BY E14,TK14. E3 AVAILABLE.

Structure

STRUCTURE TYPE: 6 Open platform (e.g., piers)
BUILDING STATUS: 2 In normal use
STORIES:
At or above Grade:2 Below Grade:0 Origin:2
FLAME DAMAGE PERCENTAGE:
<25:0 25 to 49:0 50 to 75:0 >75:0
FIRE SPREAD: 1 Confined to Object of Origin
FLAME SPREAD: None
MAIN FLOOR SIZE:
DETECTORS: 1 Smoke, U Undetermined, U Undetermined
AUTOMATIC EXT. SYSTEM: None
Hydrant w/in 1000 FT: Yes

Responding Units

Apparatus: DISTRICT CHIEF 2, Dispatched: 04/20/2024 11:43:22, En route: 04/20/2024 11:45:56, Arrival: 04/20/2024 11:50:33, Available: 04/20/2024 11:58:50
Apparatus: ENGINE 1, Dispatched: 04/20/2024 11:43:22, En route: 04/20/2024 11:45:40, Arrival: 04/20/2024 11:52:27, Available: 04/20/2024 11:58:49
Apparatus: ENGINE 14, Dispatched: 04/20/2024 11:43:22, En route: 04/20/2024 11:44:58, Arrival: 04/20/2024 11:50:28, Available: 04/20/2024 12:27:38
Apparatus: RESCUE 3, Dispatched: 04/20/2024 12:01:49, En route: 04/20/2024 12:01:58, Arrival: 04/20/2024 12:05:07, Available: 04/20/2024 12:21:16
Apparatus: TRUCK 14, Dispatched: 04/20/2024 11:43:22, En route: 04/20/2024 11:45:16, Arrival: 04/20/2024 11:51:29, Available: 04/20/2024 12:27:09

Exposures

Local

User1: 02
User2: F12

Crew Signatures

Signed by GAINEY, CHRISTOPHER [redacted] at 04/20/2024 18:39:40

REDACTED PUBLICATION COPY | Residential address removed

TAMPA FIRE RESCUE
808 Zack St.
Tampa, Florida 33602

TAMPA FIRE RESCUE

Incident 240027274

Incident Date: 04/20/2024 11:42:38
Incident Number: 240027274
Incident Location:
[redacted]
Tampa, Hillsborough, FL 33629
ENGINE 3; Shift: A

INCIDENT #: 240027274 EXPOSURE #: 000
INCIDENT LOCATION: [redacted]
INCIDENT TYPE: 112 Fire in structure, other than in a building. Included are fires on or in piers, quays, or pilings: tunnels or underground connecting structures; bridges, trestles, or overhead elevated structures; transformers, power or utility vaults or equipment; fences; and tents.
ALARM: 04/20/2024 11:42:38
DISPATCH: 04/20/2024 11:43:22
EN ROUTE: 04/20/2024 11:46:00
FIRST RESPONDER ARRIVES: 04/20/2024 11:50:28
ARRIVAL: 04/20/2024 11:50:33
CONTROL: 04/20/2024 12:11:00
LAST UNIT CLEARED:04/20/2024 12:11:00
ACTION TAKEN:73 Provide manpower ; ;
RESPONDING UNITS:
Suppression [Apparatus:1 Personnel:4]
EMS [Apparatus:1 Personnel:3]
Other [Apparatus:3 Personnel:10]
DETECTOR ALERTED OCCUPANTS: No
HAZMAT RELEASE: N None
MIXED PROPERTY USE: 40 Residential Use
PROPERTY USE: 419 1 or 2 family dwelling
No mutual aid given or received
Lead Crew Member: GAINEY, CHRISTOPHER [redacted]
Crew Member 2: PIZANO, RAFAEL [redacted]
Crew Member 3: FRYDRYCH, WILLIAM [redacted]
Crew Member 4: WILL, EVAN [redacted]

Fire Details

INVOLVED:
Living Units:1 Buildings:1
SIGNIFICANT ONSITE PRODUCTS: None
()
AREA OF FIRE ORIGIN: UU Undetermined
HEAT SOURCE: UU Undetermined
ITEM FIRST IGNITED: UU Undetermined
FIRE CONFINED TO OBJECT OF ORIGIN: Yes

REDACTED PUBLICATION COPY | Residential address removed